# **ARM KITS**

Please contact Purex additional support



### 38mm ø Arms / Arm Kits

### 120129 38mm ø x 0.7m

CONNECTOR -→ MACHINE

1x 650mm stainless steel arm (120192) 1x Reducer (40.5mm inner/outer diameter) (550265) 1x Reducer 54mm to 38mm valve to flexiarm (840112) 1x Knob knurled m4 (630305) 1x Nut insert (720600)

### 120128

38mm ø x 1.5m

CONNECTOR -

1x Reducer (40.5mm inner/outer diameter) (550265) 1x Reducer 54mm to 38mm valve to flexiarm (840112) 1x Nut insert (720600) 1x Knob knurled m4 (630305) 1x Stainless steel arm (570110)

#### 120178

38mm ø x 0.36m

1x Bench support & anti-static valve (840047) 1x Pen nib nozzle (840170) 1x 38mm stainless steel arm (570113) 1x Nut insert (720600) 1x Knurled thumb knob (630305) 1x Reducer 54mm to 38mm (840112)

#### 120151

38mm ø x 1m YOURS PROCESS ← 🗍 📗 → MACHINE

> 1x Conical cowl 38mm (95 inner diameter) (840170) 1x Stainless steel arm (120183)

### 120150

38mm ø x 1m

YOURS PROCESS ← ☐ [] → MACHINE

1x Conical cowl 38mm (95 inner diameter) (840190) 1x Metal flexiarm (120183)

#### 120149

38mm ø x 1m

1x 38mm Arm 1m long (120183) 1x Bench support & valve (840047)

### 100045

YOUR PROCESS - I III III II II ■ ■ ■ → MACHINE YOUR PROCESS - I III III III III III

1 x 100mm pipe coupling male (540120)

1 x Reducer 100mm to 80mm (540150)

2 x 38mm steel arm (120149)

1 x Dual manifold - aluminium (120093) 2 x Clamp bench bracket (120180)

2 x Delta cowl (840182)

2 x Earth strap (105054)

8m x Flexihose antistatic (570042)

4 x Machined cuff 50mm anti-static black (570211)

2 x M4 external washer (730310)

2x Self tapping screws (700111)

YOUR PROCESS — 📹 📖 🛅 ■ ■ ■ → MACHINE YOUR PROCESS - = 38mm ø x 1m

1x 100mm pipe coupling male (540120)

1x Reducer 100mm to 80mm (540150)

2x 38mm steel arm (120149)

1x Dual manifold - aluminium (120093) 2x Clamp bench bracket (120180)

2x Delta cowl (840182)

2x Earth strap (105054)

6m x Flexihose antistatic (570042) 4x Machined cuff 50mm anti-static black (570211)

2x M4 external washer (730310)

2x Self tapping screws (700111)

#### 100041

☐ → MACHINE YOUR PROCESS 🗕 🚄 👊 📠 🗓

1x Dual manifold - aluminium (120093)

2x Clamp bench bracket (120180)

2x 38mm steel arm (120149)

2x Delta cowl (840182) 2x Earth strap (105054)

6m Flexihose antistatic (570042)

4x Machined cuff 50mm anti-static black (570211) 2x M4 external washer (730310)

2x Self tapping screws (700111)

### 100295F YOUR PROCESS

38mm ø x 1m

MACHINE

2m x Flexihose antistatic (570042)

1x Clamped bench bracket (120180) 1x Pen nib nozzle 38mm (840170)

1x Conical cowl 38mm (840190)

1x Flexi arm only 1m long (120183) 2x Machined cuff 50mm anti-static black (570211)

2x Earth strap (105054)

4x M4 external washer (730310)

1x ESD kit fitting instructions (820521)


1x Bench support collar & valve anti-static (840047) 2x Earth strap screw (700316)


# **ARM KITS**

Please contact Purex additional support



## 38mm ø Arms / Arm Kits







# **ARM KITS**


Please contact Purex additional support



## 50mm ø Arms / Arm Kits







## 75mm ø Arms / Arm Kits

